

# Service Bulletin

T J A

Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990

**mazda**

Category S	Applicable Model/s 1988-'91 626/MX-6	Subject POWER DOOR LOCKS MALFUNCTION	Bulletin No. 018/91 Issued 11/22/91 Revised
---------------	--	---	---

## DESCRIPTION

A driver's side door lock that does not lock or unlock the remaining doors may have a damaged circuit in the door lock switch.

Modified switches have been installed in production vehicles starting June 3, 1991 (Hofu production) and June 25, 1991 (Flat Rock production). **These modified switches are not interchangeable** with switches on vehicles produced prior to June 3rd and June 25th respectively.

Vehicles produced prior to June 3rd and June 25th that experience this driver door lock problem, should have switches replaced with the original switch. The replacement switch must be water-proofed to prevent problem reoccurrence. See Repair Procedure for instructions.

## VIN OF PRODUCTION CHANGE

Japan Made - 626/MX-6  
USA Made - 626

JM1GD◆◆◆◆M1917355  
1YVGD22B8M5186161


June 3, 1991  
June 25, 1991

## REPAIR PROCEDURE

1. Inspect switch. See Section 14 or S of the Workshop Manual.
2. If necessary, replace the driver's door lock switch. See Workshop Manual for replacement procedures. **Figure 1.**

### NOTE:

The modified parts are not interchangeable with the original parts. Refer to the VIN and Parts Information for correct model-to-parts application.



**Figure 1: Power Door Lock Switch  
(Driver's Door)**

**IMPORTANT:** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature \_\_\_\_\_

Service Manager


Index # **025896**

Signature \_\_\_\_\_

Parts Manager

Number: 018/91	Date Issued: 11/22/91	Date Revised:
----------------	-----------------------	---------------

3. Using Three-Bond Synthetic Rubber-Type Adhesive (1521) or equivalent (silicon sealer), apply adhesive around the attaching nuts. **Figure 2.**
4. Allow adhesive to dry for about 10 minutes. Install the door lock mechanism and the door panel.



**Figure 2: Applying Adhesive to Switch**

#### PARTS INFORMATION

PART NUMBER		DESCRIPTION	QTY	APPLICABLE MODEL
MODIFIED	ORIGINAL			
G212 58 312A (Vehicles produced on or after June 3rd)	G212 58 312 (Vehicles produced prior to June 3rd)	Left Front Door Lock Switch	1	1988-'91 626
GJ24 58 312A (Vehicles produced on or after June 25th)	GJ24 58 312 (Vehicles produced prior to June 25th)	Left Front Door Lock Switch	1	1988-'91 MX-6

#### WARRANTY INFORMATION

Warranty Type Code: A  
 Customer Comment Code: 41 or 42  
 Damage Code: 93  
 Quantity: 1  
 Part No. of Main Cause: G212 58 312A or GJ24 58 312A  
 Operation No: S1007XRX  
 Labor Hours: 0.4 Hr.