

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990



Category N	Applicable Models 1988-92 626/MX-6	Subject RATTLING NOISE FROM THE POWER STEERING RESERVOIR	Bulletin No. 003/93 Issued 11/5/93 Revised
---------------	---------------------------------------	--	--

APPLICABLE MODELS/VINS

1988 through 1992 626 and MX-6 vehicles


DESCRIPTION

A rattling noise heard from the front passenger side of the vehicle may be caused by the power steering reservoir mounting pin and the lower mounting bracket locator hole. The noise is difficult to duplicate and is most evident during cold engine starts.

NOTE: Service Managers should copy this bulletin and place it in the Noise, Vibration and Harshness Manual.

REPAIR PROCEDURE

1. Verify that the complaint is not coming from another part of the vehicle.
2. Remove the 2 mounting bolts from the bottom of the power steering reservoir.
3. Lift the reservoir to access the lower mounting bracket.
NOTE: When raising the reservoir, take care not to spill the power steering fluid on painted surfaces. If fluid does spill, clean up immediately.
4. Insert grommet into the locator hole in the lower mounting bracket.
5. Lubricate the grommet to facilitate installation of the locator pin on the reservoir.
6. Install the two mounting bracket bolts.



PARTS INFORMATION

Part Number	Description
G211 32 425	Rubber Grommet

WARRANTY INFORMATION

(Applies To Vehicles Covered Under Normal Warranty)

Warranty Type: A
Customer Comment Code: 82
Damage Code: 99
Part Number Main Cause: G211 32 425
Quantity: 1
Operation Number: XX0594RX
Labor Hours: 0.4Hrs.

Index # 036598

IMPORTANT: Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Service Manager

Signature _____

Parts Manager