

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990

MAZDA

Category S	Applicable Model/s 1988-'91 626	Subject PASSIVE SHOULDER BELT DOOR SWITCH HARNESS MODIFICATION	Bulletin No. 013/91 Issued 8/8/91 Revised
---------------	------------------------------------	--	---

DESCRIPTION

Replacement passive shoulder belt assemblies have a red/yellow wire from the limit switch connector. This wire plugs into the door catch connector on 1988 and '89 626 models.

There is no car-side harness plug for this wire on 1990 and '91 626 models. When replacing this assembly on 1990 and '91 626's, cut the wire and tape it to prevent short circuits from occurring. **Figure 1.**

NOTE:

Red/yellow wire applies to 1988 and 1989 626 models only.




Figure 1: Door Switch Harness Wire Location

PARTS INFORMATION

PART NUMBER	DESCRIPTION	APPLICABLE MODEL
GJ35 57 930E	Right Passive Shoulder Belt Assy.	1988-'91 626, 4-Door
GJ35 57 990E	Left Passive Shoulder Belt Assy.	1988-'91 626, 4-Door
GJ40 57 930E	Right Passive Shoulder Belt Assy.	1988-'91 626, 5-Door
GJ40 57 990E	Left Passive Shoulder Belt Assy.	1988-'91 626, 5-Door

IMPORTANT: Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Service Manager

Signature _____

Parts Manager

024212