

# Service Bulletin

Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990

# MAZDA

Category S	Applicable Model/s 1988-'90 626/MX-6	Subject INOPERATIVE SEAT HEIGHT ADJUSTER	Bulletin No. 020/91 Issued 12/12/91 Revised 12/18/91
---------------	--	---	--

## DESCRIPTION

Some 626/MX-6 driver's seats may not adjust up or down. This is caused by a broken seat height adjuster.\*

The height adjuster unit has been changed and included into production as of August, 1990. Vehicles having this problem that were produced prior to August, 1990 should have the new adjuster unit installed.

### NOTE:

This does not effect the seat back adjustment.

## VIN OF PRODUCTION CHANGE

Japan Made JM1GD◆◆◆M1901140 August, 1990  
USA Made 1YVGD◆◆◆L5257399 August, 1990

## REPAIR PROCEDURE

Replace the driver's seat adjuster unit according to procedures in Section S or 14 of your Workshop Manual.

## PARTS INFORMATION

PART NUMBER	DESCRIPTION	APPLICABLE MODEL
GK88 88 61XA	Adjuster Unit	1988-'90 626
GJ23 88 61XA	Adjuster Unit	1988-'90 MX-6

## WARRANTY INFORMATION

Warranty Type Code: A  
Customer Comment Code: 82  
Damage Code: 9G  
Part No. of Main Cause: GK88 88 61XA (626)  
GJ23 88 61XA (MX-6)  
Quantity: 1  
Operation No./Labor Hour: S0913ARX/0.7 Hr. (one [1] seat)  
S0913BRX/1.2 Hr. (two [2] seats)

### NOTE:

Repairs allowed only within normal vehicle warranty coverage.

\* The revised section is indicated by an asterisk. Please replace the original bulletin with this revised bulletin.

**IMPORTANT:** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature .....

Signature .....

Index : 025898 Service Manager

Parts Manager