

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990



Category U	Applicable Model/s (see below)	Subject A/C ODOR	Bulletin No. 015/92
			Issued 7/21/92
			Revised

APPLICABLE MODELS

1990 323/Protegé
1988-'90 626/MX-6
1990 MX-5 Miata
1986-'90 B-Series

DESCRIPTION

A musty odor may be emitted from the ventilators after switching the A/C "ON" or "OFF." This is due to mildew forming on the evaporator core.

Cores have been modified with a resin coating which resists mildew. This new resin coated evaporator core was installed during production between April (MX-5 and B-Series) and May (323/Protegé, 626/MX-6) 1990.

Vehicles built prior to the above dates experiencing this symptom should have the modified evaporator installed. Replace the A/C evaporator according to procedures in the appropriate Workshop Manual section 16 or U.

Contact your District Service Manager for an authorization number before beginning work.

PARTS INFORMATION

PART NUMBER		DESCRIPTION	APPLICABLE MODEL
NEW	OLD		
BR70 61 J10A	BR70 61 J10	Evaporator	1990 323/Protegé
GJ51 61 J10B	GJ51 61 J10	Evaporator	1988-'90 626/MX-6
NA01 61 J10A	NA01 61 J10	Evaporator	1990 MX-5 Miata
0000 67 B31A 0P	0000 67 B31A 6P	Evaporator	1986-'90 B-Series

IMPORTANT: Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Signature _____

.....
Service Manager

Parts Manager

Index : **030189**

Page 1 of 2

Number: 015/92	Date Issued: 7/21/92	Date Revised:
----------------	----------------------	---------------

WARRANTY INFORMATION

(Applies to vehicles covered under warranty.)

Warranty Type Code: Q
Customer Comment Code: A5
Damage Code: AE

Part No. of Main Cause:

323/Protegé BR70 61 J10A
626/MX-6 GJ51 61 J10B
MX-5 Miata NA01 61 J10A
B-Series 0000 67 B31A 0P

Quantity: 1

Related Part Number: 0000 00 0837 (Refrigerant)

Quantity: 2

Operation No/Labor Hour:

(Evaporator R&R)

323/Protegé U0604XRX / 0.6 Hrs.
626/MX-6 U0604XRX / 0.6 Hrs.
MX-5 Miata U0604XRX / 0.6 Hrs.
B-Series U0604XRX / 0.5 Hrs.

(Evacuation & Recharge)

All Models U0003XRX / 0.5 Hrs.

NOTE:

An authorization number must be obtained from your District Service Manager prior to evaporator core replacement.