

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990

MAZDA

Category 16	Applicable Model/s 1988-1989 626/MX-6	Subject "REC-FRESH" LEVER	Bulletin No. 037/88 Issued 12/7/88 Revised
----------------	---	------------------------------	--

DESCRIPTION

If a customer complains that the manually operated "Rec-Fresh" control becomes hard to operate in the modes listed below, replace cases "A" and "B" and the "Rec-Fresh" door of the blower unit with the modified parts listed in this bulletin.

More than 55 mph approx.	Hard to change "Fresh" → "Rec"
Blower set in 4th speed	Hard to change "Rec" → "Fresh"

Modified parts have been incorporated into production vehicles since September 1988.

VIN OF PRODUCTION CHANGE

JM1GD★★★★ K1716188 September, 1988

PARTS INFORMATION

PART NUMBER		DESCRIPTION	INTERCHANGEABILITY
NEW	OLD		
GJ21 61 140E	GJ21 61 140D	Blower Unit	NEW → OLD
GJ21 61 B01A	GJ21 61 B01	Case "A"	NEW+P → OLD
GJ21 61 B02A	GJ21 61 B02	Case "B"	NEW+P → OLD
GJ21 61 B05	---	"Rec-Fresh" Door	---

NOTE:

When ordering new blower unit cases the "Rec-Fresh" door MUST be ordered also.

IMPORTANT Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

013595

Signature _____

Service Manager


Signature _____

Parts Manager

Number: 037/88

Date Issued: 12/7/88

Date Revised:



WARRANTY INFORMATION

Customer Comment Code: 7J
Damage Code: 83
Part No. of Main Cause: GJ21 61 B05
Operation No: XX0307RX
Labor Hours: 0.7