

Service Bulletin

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990

mazda

Category B	Applicable Model/s 1988-'91 626/MX-6 A/T	Subject IDLE VIBRATION IN DRIVE	Bulletin No. 010/91 Issued 10/3/91 Revised
---------------	--	------------------------------------	--

DESCRIPTION

The steering wheel and seat on some 626/MX-6 vehicles may vibrate too much while idling in drive ("D"). The vibrations may be stronger when an electrical load is applied (headlamps, wipers, etc.). This may be caused by a combination of engine and radiator mounts.

To correct this problem, install new engine and radiator mounts using the Inspection and Repair Procedure below. New engine and radiator mounts are now installed during production (see VIN of Production Change below).

NOTE:

This Service Bulletin replaces Service Bulletins, Category 1, No. 042/89 and Category B, No. 001/90.

VIN OF PRODUCTION CHANGE

No. 1 & 2 Engine Mounts

1991	JM1GD◆◆◆◆M1902957	October 1, 1990
	1YVGD◆◆◆◆M5131853	November 7, 1990

Lower Radiator Mount

1989 Non-Turbo	JM1GD◆◆◆◆K1769601	June 1, 1989
	1YVGD◆◆◆◆K5245888	June 24, 1989
1991 Turbo	JM1GD◆◆◆◆M1901869	September 1, 1990
	1YVGD◆◆◆◆M5120718	October 2, 1990

INSPECTION & REPAIR PROCEDURE

1. If the steering wheel and seat vibrate too much at idle, perform the following steps.
2. Check if idle speed is 725-775 rpm in "P." If not, adjust it to 750 rpm with test connector grounded.
3. Install new lower radiator mounts.
4. Center the radiator stud in the damper of the radiator upper bracket. See Section "3" or "E" of the Workshop Manual.

IMPORTANT: Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature _____

Service Manager

Signature _____

Parts Manager

024546

Page 1 of 3

5. If necessary, move the A/C pipe away from the radiator. **Figure 1.**
6. If hood rattles, adjust the hood lock.
7. Install new No. 1 and No. 2 engine mounts. See Section "1" or "B" of the Workshop Manual.




Figure 1: Check A/C Pipe at Area Shown

8. Remove and discard the muffler hangers and rubbers. **Figure 2.**
9. Install the hanger bolts into the body to prevent water entry.
10. If the steering wheel and seat still vibrate too much, ground the test connector. Adjust idle speed to 950–1000 rpm in "P." Disconnect the test connector.




Figure 2: View of Muffler Hangers & Rubbers

PARTS INFORMATION

PART NUMBER	DESCRIPTION	APPLICABLE MODEL
M002 39 040B	No. 1 Engine Mount	Non-Turbo
GJ28 39 040E	No. 1 Engine Mount	Turbo
GJ23 39 050C	No. 2 Engine Mount	All
F202 15 202B	Lower Radiator Mount	All

Number: 010/91	Date Issued: 10/3/91	Date Revised:
----------------	----------------------	---------------

WARRANTY INFORMATION

Warranty Type Code: A
 Customer Comment Code: 83
 Damage Code: 97
 Part No. of Main Cause: No. 1 Engine Mounts
 M002 39 040B (Non-Turbo)
 GJ28 39 040E (Turbo)
 No. 2 Engine Mounts
 GJ23 39 050C (All)
 Lower Radiator Mount
 F202 15 202B (All)
 Operation No. & XX0376RX (Includes R&R of No. 1 & No. 2 Engine Mounts)
 Labor Hour: 1.0 Hr.
 XX0331R2 (All repairs except R&R of No. 1 & No. 2 Engine Mounts)
 0.4 Hr.