

# Service Bulletin

1 Jan 4/88  
Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990


**MAZDA**

Category 4	Applicable Model/s 1989 323, 626, 929 & MPV (3.0L)	Subject ENGINE STALL WHEN E.C.U. IS COLD	Bulletin No. 064/89 Issued 12/15/89 Revised
---------------	--	---	---

## DESCRIPTION

1989 323, 626, 929 and MPV (3.0L) models produced between November 1988 and January 1989 may exhibit the following problem in temperatures of less than 0°C.

The problem is that the engine starts while the I.G. key is turned to the "START" position, but immediately stalls when the key is returned to the "ON" position. This occurs only when the temperature of the Emission Control Unit (E.C.U.) is approximately 0°C or less. However, the engine operates normally when the temperature is higher than 0°C.



Problem Phenomenon

## REPAIR PROCEDURE

1. Verify whether the engine stalls under the above condition.
2. Replace the E.C.U. if the problem is observed.

**IMPORTANT** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature \_\_\_\_\_

Service Manager

Signature \_\_\_\_\_

Parts Manager

016952

Number: 064/89	Date Issued: 12/15/89	Date Revised:
----------------	-----------------------	---------------

#### AFFECTED VIN RANGE

1989 929: JM1HC★★★★K0210413-217879  
 1989 626: JM1GD★★★★K1731830-746266  
           1YVGD★★★★K5212570-225932  
 1989 323: JM1BF★★★★K0343911-370717  
 1989 MPV (3.0L): JM3LV★★★★K0110558-121417

#### PARTS INFORMATION

REBUILT P/N	APPLICABLE MODEL	FED/CA
B6K1 18 881R B6B3 18 881R B6K2 18 881R B6B4 18 881R	'89 323 - Non-Turbo Turbo Non-Turbo Turbo	Federal Federal California California
F201 18 881R F220 18 881R F225 18 881R F203 18 881R F222 18 881R F226 18 881R	'89 626 - Non-Turbo 2WS Turbo 2WS Turbo 4WS Non-Turbo 2WS Turbo 2WS Turbo 4WS	Federal Federal Federal California California California
JEY6 18 881R JEY7 18 881R	'89 929	Federal California
JE15 18 881R	'89 MPV (3.0L)	

#### WARRANTY INFORMATION

Customer Comment Code: 1E  
 Damage Code: 63  
 Process No: B9008A  
 Part No. of Main Cause: Use applicable ECU part number.  
 Operation No: F0812X-R-X  
 Labor Hour: 0.4 Hr. (929 - 0.5 Hr.)