

Service Bulletin

12-14-89

Mazda Motor of America, Inc.
7755 Irvine Center Drive
Irvine, California 92718
Telephone (714) 727-1990


mazda

Category 14	Applicable Model/s (see below)	Subject SUNVISOR ADJUSTMENT	Bulletin No. 060/88 Issued 11/4/88 Revised
----------------	-----------------------------------	---------------------------------------	--

DESCRIPTION

On 1988-89 323, 626/MX-6, or B2200/2600 models you may notice problems during PDI or encounter customer complaints regarding sunvisor operation (i.e. sunvisor will not adjust up or down, or will not remain at a set position).

Check the adjustment screw (as shown) prior to replacement. Adjust the screw to enable the driver and/or passenger to rotate the sunvisors to any set position.



IMPORTANT Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned

013586

Signature _____

Service Manager

Signature _____

Parts Manager