

# Service Bulletin

Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990

**mazda**

Category ST	Applicable Model/s All 1988-95 Models	Subject SHIPMENT OF NGS PROGRAM CARD VERSION 2.0	Bulletin No. 002/94 Issued 10/25/94 Revised 11/16/94
----------------	---	--	--

The revised portion of this bulletin is indicated by an asterisk (\*). Replace the original bulletin with this revised copy

## DESCRIPTION

The "NGS Program Card" (P/N 49T0-88-010) used with your New Generation Star tester has been discontinued. The card is replaced with a new card that includes all 1995 model information.

This new program card "Version 2.0" (P/N 49T0-88-010A) is a MRT (Minimum Required Tool) and will automatically be shipped to all dealers on October 26, 1994 by Mazda's tool vendor, America Kowa Seiki, Inc. The cost of the new card is \$235.75. This cost will be charged to your parts account upon its receipt.

**NOTE:** 1) Please advise your shipping/receiving personnel of this shipment.

- 2) **This program card is small.** Therefore, we recommend that your service manager, shop foreman, or lead technician install this card in your NGS tester and discard the discontinued card immediately. This will prevent misapplication or misdiagnosis when using the NGS tester to service a Mazda vehicle.

## APPLICATION

Refer to the attached table for applications of this new card.

If you have any questions regarding this information contact your District Customer Support Manager or Tools/Development Manager at (714) 588-5059.

**IMPORTANT:** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature \_\_\_\_\_  
Service Manager

Signature \_\_\_\_\_  
Parts Manager

Page 1 of 2

059153

Number: 002/94	Date Issued: 10/25/94	Revised: 11/16/94
----------------	-----------------------	-------------------

**\*APPLICATION TABLE FOR NGS PROGRAM CARD VERSION 2.0 (P/N 49T0-88-010A)**

NOTE	APPLICABLE MODEL	PCM* <sup>1</sup>	TCM* <sup>2</sup>	ABS	A/C	CCM* <sup>3</sup>
	1995 MILLENIA	O* <sup>4</sup>	(O)	O* <sup>5</sup>	O	O
X	1995 PROTEGE	O* <sup>4</sup>	(O)	O	-	O
X	1995 626/MX-6 WITH FS ENGINE	O	-	O	-	O
X	1995 626/MX-6 WITH KL ENGINE	O	O	O	-	O
X	1995 929	O	O	O	O	O
X	1995 MX-3	O	O	O	-	-
X	1995 MIATA	O	O	O	-	-
X	1995 RX-7	O	O	O	-	O
X	1995 MPV	O	O	-	-	-
X	1995 B2300, B3000, B4000	O* <sup>4</sup>	(O)	O	-	-
	1994 323/PROTEGE	O	O	-	-	-
	1994 626/MX-6 WITH FS ENGINE (EC-AT)	O	(O)	O	-	O
	1994 626/MX-6 WITH FS ENGINE (MT)	O	-	O	-	O
	1994 626/MX-6 WITH KL ENGINE	O	O	O	-	O
	1994 929	O	O	-	O	O
	1994 MX-3	O	O	O	-	-
	1994 MIATA	O	O	O	-	-
	1994 RX-7	O	O	-	-	-
	1994 MPV WITH G6 ENGINE	O	O	-	-	O
	1994 MPV WITH JE ENGINE	O	O	-	-	-
	1994 NAVAJO	O	(O)	-	-	-
	1994 B2300 2.3L (49S)	O	(O)	O	-	-
	1994 B2300 2.3L (CAL)	O	(O)	-	-	-
	1994 B3000 & B4000	O	(O)	-	-	-
	1993 NAVAJO	O	-	O	-	-
	1992 - 1993 ALL VEHICLES EXCEPT NAVAJO	O	O	O	O	O
	1991 - 1992 NAVAJO	O	-	-	-	-
	1991 ALL VEHICLES EXCEPT NAVAJO	O	O	-	-	-
	1988 - 1990 ALL VEHICLES	O	O	-	-	-

\*1: PCM= Power Control Module

\*2: TCM= Transmission Control Module

\*3: CCM= Cruise Control Module

\*4: on-vehicle control unit equipped with OBD-II

\*5: include Traction Control System

(O): means there is no TCM, but it is possible to diagnose the TCM from the PCM menu.

X: means these year/models are newly added to the program card.