

# Service Bulletin

Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990

# MAZDA

Category 14	Applicable Model/s 1988-1989 626/MX-6	Subject CENTER CONSOLE LID LOCK	Bulletin No. 069/89 Issued 9/1/89 Revised
----------------	---	------------------------------------	---


## DESCRIPTION

On some of the 1988-1989 626/MX-6 models on which the console lid had been replaced with an accessory arm-rest, the hinge pin of the console lid lock may be loose and create a rattling noise because no stopper had been attached to the accessory arm-rest.

If you encounter this problem, replace the lock plate in the accessory arm-rest with a modified one.

## PARTS INFORMATION

PART NUMBER		DESCRIPTION
NEW	OLD	
GJ30 V0 636A	GJ30 V0 636	Lock Plate



016004

**IMPORTANT** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature \_\_\_\_\_  
Service Manager

Signature \_\_\_\_\_  
Parts Manager