

# Service Bulletin

Mazda Motor of America, Inc.  
7755 Irvine Center Drive  
Irvine, California 92718  
Telephone (714) 727-1990

# MAZDA

Category 14	Applicable Model/s All Models	Subject STATIC ELECTRICITY SHOCK	Bulletin No. 067/89 Issued 3/29/89 Revised
----------------	----------------------------------	-------------------------------------	--



## DESCRIPTION

Drivers or passengers may occasionally feel static electricity shock when they touch the door after getting out of the vehicle.

If you encounter the customer complaint on the above condition, spray anti-static agent to the surface of the seat cushion and back trim.

The following anti-static agents are recommended for static electricity shock on Mazda vehicles.

MANUFACTURER	PRODUCT
Tech Spray	Anti-stat
National System Corporation	antistat
ACL Incorporation	Staticide
Chemtronics Inc.	Static Free

Before using the spray, carefully read the instructions of each product.

**IMPORTANT** Service and Parts Managers should read this bulletin carefully, sign and convey all information to those concerned.

Signature \_\_\_\_\_

Service Manager

Signature \_\_\_\_\_

Parts Manager

014697